

# Ackerman, Joyce

From:

Thomas J. Krasovec <TJKrasovec@Geosyntec.com>

Sent:

Thursday, February 15, 2018 4:16 PM

To:

Ackerman, Joyce

Subject:

RE: Neuhauser - sample tracking log?

Joyce,

Possibly tomorrow if not then on all is 50/50 pending weather as some of the drum sampling may be put off until Monday waiting for colder weather to keep odors down. But I should be able to firm up a bit tomorrow.

Thanks TJK

From: Ackerman, Joyce [mailto:Ackerman.Joyce@epa.gov]

Sent: Thursday, February 15, 2018 1:29 PM

To: Thomas J. Krasovec <TJKrasovec@Geosyntec.com>

Subject: RE: Neuhauser - sample tracking log?

Thanks Tom! When are the test pits to locate bedrock and take samples in 2a and 2b going to be conducted?

Joyce

From: Thomas J. Krasovec [mailto:TJKrasovec@Geosyntec.com]

Sent: Thursday, February 15, 2018 1:26 PM
To: Ackerman, Joyce < Ackerman. Joyce@epa.gov > Subject: RE: Neuhauser - sample tracking log?

Joyce,

Here it is also. Please let me know if you need anything else. Phase 3 going off site beginning today and we will be sampling drums tomorrow along with continuing Phase 3. As previously noted we will be analyzing for total VOCs full list and periodic total metals please let me know if you would like any further analyses. All of these drums are going off as hazardous waste.

Thanks

From: Ackerman, Joyce [mailto:Ackerman.Joyce@epa.gov]

Sent: Thursday, February 15, 2018 1:10 PM

To: Thomas J. Krasovec < TJKrasovec@Geosyntec.com>

Subject: Neuhauser - sample tracking log?

Hi Tom – would you please send me the sample tracking log? Thanks!

Joyce Ackerman
On-Scene Coordinator and START P.O.
U.S. EPA Region 8
1595 Wynkoop Street

Denver, CO 80202 (303) 312-6822

# Ackerman, Joyce

From:

Thomas J. Krasovec <TJKrasovec@Geosyntec.com>

Sent:

Thursday, February 15, 2018 1:26 PM

To:

Ackerman, Joyce

Subject: Attachments: RE: Neuhauser - sample tracking log?
Redtail Tracking Documents 2 15 2018.pdf

Joyce,

Here it is also. Please let me know if you need anything else. Phase 3 going off site beginning today and we will be sampling drums tomorrow along with continuing Phase 3. As previously noted we will be analyzing for total VOCs full list and periodic total metals please let me know if you would like any further analyses. All of these drums are going off as hazardous waste.

Thanks

From: Ackerman, Joyce [mailto:Ackerman.Joyce@epa.gov]

Sent: Thursday, February 15, 2018 1:10 PM

To: Thomas J. Krasovec <TJKrasovec@Geosyntec.com>

Subject: Neuhauser - sample tracking log?

Hi Tom – would you please send me the sample tracking log? Thanks!

Joyce Ackerman
On-Scene Coordinator and START P.O.
U.S. EPA Region 8
1595 Wynkoop Street
Denver, CO 80202
(303) 312-6822

			Sample Location			Notes				
Sample Name		Sample Matrix	For liquid	, soil, and sludge	Soil and s	ludge only				
						1	Include drum names if applicable	TA Job	Date of Level	Date Transmitte
			· ·	Overpack name	Drums in area	Excavation Loc.	for sampling	Number	4 Report	to EPA
		Liquid, Soil, Sludge,			(if applicable, list	(if applicable -			T .	
NLF-aa-bbbbb-cccccMMDDYY	Time	Solid Waste	Phase Area	(if applicable)	drums in area)	sidewall, floor, etc.)				
1 NLF-LW-DINV1-121217	13:45	Liquid	2A				From drum RTR-21	180-73385-1	12/22/2017	12/29/20
2 NLF-LW-DINV2-121317	16:29	Liquid	2A	RTR-29			From drum RTR-29	180-73510-1	12/24/2017	12/29/20
3 NLF-SS-DINV3-121417	10:55	Soil	2A				From drum RTR-31	180-73510-2	12/22/2017	12/29/20
4 NLF-SL-DINV4-121417	14:15	Sludge	2A	RTR-36			From drum RTR-36	180-73510-3	12/22/2017	12/31/20
5 NLF-LW-DG2-COMP1-121517	9:16	Liquid	28	Phase 2B Consolidation Drum			From drums RTR-23 and RTR-68	180-73525-1	12/26/2017	12/29/20
6 NLF-SS-CMPD1-COMP1-121517	10:02	Soil .	2A		36 and 40			180-73525-2	12/26/2017	12/29/20:
7 NLF-SS-CMPD1-COMP2-121517	10:11	Soil	2A		36 and 40			180-73525-2	12/26/2017	12/29/20
8 NLF-SS-CMPD2-COMP1-121517	10:47	Soil .	2B		69 and 75			180-73525-2	12/26/2017	12/29/20
9 NLF-SS-DG1-COMP1-121517	15:05	Soil	2A				From drums RTR-76 and RTR-78	180-73525-2	12/26/2017	12/29/20
10 NLF-SS-DG2-DINVS-121617	10:00	Soil/Solid	2B	RTR-75			From drum RTR-75	180-73597-1	12/28/2017	12/29/20
11 NLF-LW-DG1-DINV6-121617	10:23	Liquid	2A	RTR-55			From drum RTR-55	180-73597-2	12/27/2017	12/29/20
12 NLF-SS-DG1-DINV7-121617	13:20	Soil	2A	Phase 2A Consolidation Drum			From drum RTR-60	180-73597-1	12/28/2017	12/29/20
13 NLF-LW-DG1-DINV8-121617	15:00	Liquid	2A	RTR-63			From drum RTR-63	180-73597-2	12/27/2017	12/29/20
14 NLF-SS-DG2-COMP2-121717	10:54	Soil	2B				From drums RTR-74, 75, 76, 77, and 84	180-73597-1	12/28/2017	12/29/20
15 NLF-SS-CMPD2-COMP2-121817	9:28	Soil	2B		23 and 67			180-73597-1	12/28/2017	12/29/20
16 NLF-SS-DG1-DINV9-121817	12:04	Soil	2 <b>A</b>		•		From drum RTR-140	180-73597-1	12/28/2017	12/29/20
17 NLF-SS-DG1-DINV10-121817	10:50	Soil	2A				Duplicate of NLF-SS-DG1-DINV9- 121817	180-73597-1	12/28/2017	12/29/20
18 NLF-SS-CMPD1-COMP3-121817	15:20	Soil	2A				Collected MS/MSD. Collected from base of Phase 2A excavation	180-73622-1	12/29/2017	1/3/20
19 NLF-SS-PHASE3-TP1-121817	16:07	Soil	3				Test Pit 1, about 10 feet south of MW-2, about 9 feet deep	180-73622-1	12/29/2017	1/3/20

				-	Samp	le Location		Notes			
	Sample Name		Sample Matrix	For liquid	, soil, and sludge	Soil and slu	udge only				
								Include drum names if applicable	TA Job	Date of Level	Date Transmitted
					Overpack name	Drums in area	Excavation Loc.	for sampling	Number	4 Report	to EPA
			Liquid, Soil, Sludge,			(if applicable, list	(if applicable -			<u> </u>	
	NLF-aa-bbbbb-cccccMMDDYY	Time	Solid Waste	Phase Area	(if applicable)	drums in area)	sidewall, floor, etc.)			ļ	
								Test Pit 1, about 2 feet south of			
20	NLF-SL-PHASE3-TP1-121817	16:10	Sludge	3	*			MW-2, about 9 feet deep	180-73622-1	12/29/2017	1/3/2018
				1				Test Pit 2, about 4 feet north of			
21	NLF-SL-PHASE3-TP2-121917	8:30	Sludge	3				SEC MW-2, about 9 feet deep	180-73622-1	12/29/2017	1/3/2018
				1				Test Pit 3, about 10 feet SW of SEC			
22	NLF-SL-PHASE3-TP3-121917	9:05	Sludge	3				MW-2, about 9 feet deep	180-73622-1	12/29/2017	1/3/2018
								Test Pit 4, about 10 feet south of			
23	NLF-SL-PHASE3-TP4-121917	9:30	Sludge	3				SEC MW-2, about 9 feet deep	180-73622-1	12/29/2017	1/3/2018
				i .				Test Pit S, about 10 feet SE of SEC			
24	NLF-SL-PHASE3-TP5-121917	9:52	Sludge	3				MW-2, about 10 feet deep	180-73622-1	12/29/2017	1/3/2018
		'									
25	NLF-SS-CMPD2-COMP3-121917	14:30	Soil	2B				Soil from excavation bottom	180-73685-1	1/4/2018	
								Liquid that leaked out of RTR-153			
								and pooled at bottom of			
26	NLF-LW-DG1-DINV11-121917	14:52	Liquid	2A			<u>.                                    </u>	excavation	180-73685-2	12/29/2017	1/3/2018
			·	·							
27	NLF-SL-DG2-COMP3-122017	13:40	Sludge	2B				RTR-72, RTR-73, RTR-86, RTR-101	180-73685-1	1/4/2018	
			- "					RTR-67, RTR-87, RTR-96, RTR-100,		4/4/2040	
. 28	NLF-SS-DG2-COMP4-122017	13:50	Soil	2B				RTR-103 RTR-155, RTR-45, RTR-134, RTR-	180-73685-1	1/4/2018	
20	NUE CL DC1 CON103 133013	14.00	Sludge	2A				147	180-73685-1	1/4/2018	
	NLF-SL-DG1-COMP2-122017	14:00	Sluage	ZA				147	180-73685-1	1/4/2018	
20	NLF-SS-DG1-DINV12-122017	14:55	Colid	2A	· '			From drum RTR-159	180-73685-1	1/4/2018	
. 30	14LF-33-DG1-DH4V12-122017	14.33	3011d	28				710111111111111111111111111111111111111	180-73083-1	1/4/2018	
31	NLF-LW-PHASE1-DINV13-122117	10:25	Liquid .	1				From drum RTR-160	180-73707-1	1/2/2018	1/3/2018
31	VEF-EW-F/IA3E1-DRVV13-122117	10.23	Liquio .	1				7101170170111111111-100	100 /3/0/-1	1/2/2018	1/3/2010
32	NLF-SS-PHASE1-DINV14-122117	10:31	Soil	1				From drum RTR-161	180-73707-2	1/5/2018	
32	14C1-55-7 TIASE1-DIRVIY-122117	10.51	5011				<del>                                     </del>		100 /3/0/ 2	1/3/2010	
33	NLF-SS-PHASE1-DINV15-122117	14:20	Soil	1,				From drum RTR-165	180-73707-2	1/5/2018	
- 35	NEI BOTTINGEI BITTIS ILLII	220		i			-			-,-,	
34	NLF-SL-PHASE3-TP9-122217?	9:47	Sludge	3				Test Pit 9, about 12 feet bgs	180-73714-1	1/5/2018	
	THE SETTINGES HIS SEELEN.			-				Duplicate of NLF-LW-PHASE 2B-			
35	NLF-LW-PHASE2B DINV16-010418	12:34	Liquid	2B	•			DINV17-010418	180-73914-1	1/12/2017	
				1			_				
36	NLF-LW-PHASE2B-DINV17-010418	15:50	Liquid	2B	RTR-107			RTR-107	180-73914-1	1/12/2017	
					•						
37	NLF-SL-PHASE2B-DINV18-010518	10:09	Sludge	2B	RTR-109			Black jello-like sludge; RTR-109	180-73914-2	1/12/2017	

					ple Location	<del></del>	Notes		ļ	
Sample Name		Sample Matrix	For liquid	, soil, and sludge	Soil and s	ludge only	_			
			Ì				Include drum names if applicable	dol AT	Date of Level	Date Transmitt
			'	Overpack name	Drums in area	Excavation Loc.	for sampling	Number	4 Report	to EPA
		Liquid, Soil, Sludge,			(if applicable, list	(if applicable -	·		1	
NLF-aa-bbbbb-cccccMMDDYY	Time	Solid Waste	Phase Area	(if applicable)	drums in area)	sidewall, floor, etc.				
	1		}	}	l	1	·	1	1	
1							Soil sampled from 3' below surface			
38 NLF-SS-COMPD3-D1-010518	15:00	Soil	2B			ļ	on eastern side of 2B pit.	180-73914-2	1/12/2017	
								ļ	1	
					1	į.	Soil sampled from 7' below surface	1		
39 NLF-SS-COMPD3-D2-010518	15:08	Soil	2B		ļ	ļ	on southern side of 2B pit.	180-73914-2	1/12/2017	
							3 areas, 1 ft below surface, from 3	i	'	
40 NLF-SS-COMPD1-COMP1-010518	13:55	Soil	2A				locations in 2A pit, composited.	180-73914-2	1/12/2017	
•			İ				Soil sampled from 3' below			
				•			surface, 2 areas in west and north		l	
41 NLF-SS-COMPD2-COMP2-010518	14:15	Soil	2B				in 2B and composited.	180-73914-2	1/12/2017	
·		1					Soil sampled from 7' below			
					İ		surface, 2 areas in west and north			
42 NLF-SS-COMPD2-COMP3-010518	14:30	Soil	2B	. <u>.</u>	<u> </u>		in 2B and composited.	180-73914-2	1/12/2017	
							Soil sampled from directly above		1	
43 NLF-SS-COMPD3-COMP1-010518	16:14	Soil	3		]		the drums found adjacent to MW-	180-73948-3	1/16/2017	
		,	1				Black, paint like, seperated quickly.			
						ļ	Distinct thin black layer on top,		1	
		1		1		•	denser yellow/clear liquid		1	
44 NLF-LW-PHASE2B-DINV19-010618	11:26	Liquid	2B	RTR-114		Hot	beneath. RTR-114	180-73948-2	1/16/2017	
45 NLF-SL-PHASE1-DINV20-010618	12:26	Soil	1	RTR-477			Black, tar-like material. RTR-477	180-73948-3	1/16/2017	
		***					Liquid from RTR-122, but appears			
	İ					İ	to be groundwater connected with		ŀ	
46 NLF-LW-DG2-DINV20-010818	10:10	Liquid	2B	RTR-121/122	118, 121, 122	Hot	118 and 121 as well	180-73948-1	1/16/2017	
40 NET EW 002-010818	10.10	Liquid	25	1111-121/122	110, 121, 122	- 1100	210 bild 121 b3 WCII	100 73540 1	1/10/2017	
47 NLF-SS-PHASE1-DINV21-011118	15:30	Solid	-	RTR-569		i	White solid from RTR-569	180-74914-1	1/23/2017	
47 NG 337 NASCI-DINV21-011118	15.50	30110	<u> </u>		<del> </del>	<del></del>	White Solid Holli Kirk Ses	100 / 1314 1	1,25,2027	
48 NLF-SS-PHASE1-COMP4-011118	16:42	Sail				·	East soil stockpile	180-74189-1	1/19/2017	
40 NC 35 1 (IASE1-COM) 4-011110	10.42	3011	<del>                                     </del>	<del> </del>	<del>                                     </del>	<del> </del>	t t	100 / 1203 1	2,10,101	
49 NLF-SS-PHASE1-COMP1-011118	16:44	Cail	l .				Center soil stockpile	180-74189-1	1/19/2017	
45 145 -35- HASE1-COM/F1-011118	10.44	3011	<del>  '</del>	1	<del> </del>	<del> </del>	center son stockpile	100-74103-1	1,13,2017	
50 NLF-SL-PHASE1-DINV22-011218	10,33	Sludge	Ι,	RTR-573	1		Black/brown sludge from RTR-573	100 74014 1	1/23/2017	
30 NLT-3L-T MASE1-DINV22-011218	10:32	Single	·	C1C-717	<del> </del>	<del> </del>	Biack/brown studge from KTK-575	100-74914-1	1/23/2017	
ELANGE SE PROCESS ASSURE ASSURE			1 .			1 .	N. at	100 74100 1	1/10/2017	Ť
51 NLF-SS-PHASE1-COMPS-011218	14:25	Soil	1		-	+	North soil stockpile	180-74189-1	1/19/2017	
			L			1 .	Phase 2B in the area of Test Pit 9,	1		
52 NLF-SL-PHASE2B-TP9-011218	15:00	Sludge	2B	<u> </u>		<u> </u>	approximately 5 feet bgs.	180-74914-1	1/23/2017	

	,			I	Samp	ole Location		Notes	T		
	Sample Name		Sample Matrix .	For liquid,	soil, and sludge	Soil and sl	udge only				
								Include drum names if applicable	TA Job	Date of Level	Date Transmitted
					Overpack name	Drums in area	Excavation Loc.	for sampling	Number	4 Report	to EPA
			Liquid, Sail, Sludge,			(if applicable, list	(if applicable -		<u> </u>	i :	
	NLF-aa-bbbbb-cccccMMDDYY	Time	Solid Waste	Phase Area	(if applicable)	drums in area)	sidewall, floor, etc.)				
	***************************************							Dug 1' deep in three locations to			
l 5	3 NLF-SS-PHASE1-COMP6-011718	14:00	Soil	1				collect a composite sample from a	180-74221-1	1/19/2017	
		<u> </u>						Dug 1' deep in three locations to			
5	4 NLF-SS-PHASE1-COMP7-011718	14:30	Soil	1				collect a composite sample from a	180-74221-1	1/19/2017	
	1							Dug 10' deep in Test Pit P (same			
5	S NLF-SS-PHASE1-TPP-012318	14:19	Soil	1				location as Test Pit A 1/16/18) to	180-74373-1	1/25/2017	
5	6 NLF-SS-PHASE1-COMP8-012518	12:45	Soil	1				East soil stockpile			
l											
5	7 NLF-SS-PHASE1-COMP9-012518	13:00	Soil	1				Center soil stockpile			
l								Dug 1' deep in two locations to	l .		
5	8 NLF-SS-PHASE1-COMP10-012518	13:15	Soil	1				collect a composite sample from a			
1		İ	·.	]				Black paint-like liquid from RTR-			
5	9 NLF-LW-PHASE1-DINV23-012518	15:07	Liquid	2B				878.			
ļ	•			l			l .	Gray/black contaminated			
	O NLF-LW-PHASE2B-GW-013118	10:20	Liquid	28				groundwater sampled from the Black sludge found on the floor			
Ι.								1 "			
	1 NLF-SL-PHASE2B10-PITFL-020318	11:02	Sludge	28			<u> </u>	and sidewalls surrounding the			
, ا	2 NLF-SS-PHASE2B-CHRT27116-020518	9:00	coil	2B			'	From Roll-off bin CHRT27116			
F-	Z NCF-33-PHASE26-CHR12/116-020318	5.00	3011	25			<del> </del>	Trans Rail-Olf Bill Clin 27110	-		
، ا	3 NLF-SS-PHASE2B-PT5631-020518	9:05	Soil ·	2B				From Roll-off bin PT5631			
F -	5 NG -55-7 IM3E28-7 15051-020518	3.03	5011	-							
,	4 NLF-SS-PHASE2B-PT2489-020518	9:20	Soil	28				From Roll-off bin PT2489			
<u> </u>		1					<del> </del>				
,	5 NLF-SS-PHASE2B-CHRT25758-020518	9:30	Soil	28				From Roll-off bin CHRT25758	'		
<u> </u>		1									
6	6 NLF-SS-PHASE2B-CHRT25758-020518-DUP	9:30	Soil	2B	i .			From Roll-off bin CHRT25758			
		1		-			T				
6	7 NLF-SS-PHASE2B-CHRT26830-020518	9:40	Soil	28				From Roll-off bin CHRT26830			
				1							
6	8 NLF-SS-PHASE2B-CHRT25696-020518	9:50	Soil	28				From Roll-off bin CHRT25696	L	ļ	
6	9 NLF-SS-PHASE2B-CHRT24497-020518	10:00	Soil	2B				From Roll-off bin CHRT24497			
7	0 NLF-SS-PHASE2B-DRT4699-020518	10:15	Soil ,	28				From Roll-off bin DRT4699			
7	1 NLF-SS-PHASE2B-HT3702-020518	10:25	Soil	2B ·			1	From Roll-off bin HT3702			

	1	1		1	Same	ole Location		Notes		1	
	Sample Name		Sample Matrix	For liquid	, soil, and sludge	Soil and slu	udge only	Notes		<del> </del>	
	estripte visite		Sumple Mount	101 114010	Overpack name	Drums in area	Excavation Loc.	Include drum names if applicable for sampling	TA Job Number	Date of Level 4 Report	Date Transmitted to EPA
	NLF-aa-bbbbb-cccccMMDDYY		Liquid, Soil, Sludge, Solid Waste	Phase Area	(if applicable)	(if applicable, list drums in area)	(if applicable - sidewall, floor, etc.)				
72	NLF-SS-PHASE2B-DINV24-020718	15:47	Soil	28	RTR-1025			Fine grained brown solid with white powdery coating			
73	NLF-SS-PHASE2B-274734-020818	8:09	Soil	2B				From Roll-off bin 274734	·		
. 74	NLF-SS-PHASE2B-279853-020818	8:22	Soil .	2В				From Roll-off bin 279853	•	·	
75	NLF-SS-PHASE2B-279944-020818	8:45	Soil	2В				From Roll-off bin 279944			
76	NLF-SS-PHASE2B-279684-020818	9:02	Soil	2B				From Roll-off bin 279684 Yellow/clear liquid and black			
77	NLF-LW-PHASE2B-DINV25-020818	11:33	Liquid	2B	RTR-1036			liquid. Seperated into two layers	-		
78	NLF-SS-PHASE2B-279947-020818	9:30	Soil	28				From Roll-off bin 279947		<u> </u>	
79	NLF-SS-PHASE2B-279962-020818	14:44	Soil	2В		·.		From Roll-off bin 279962			
80	NLF-SS-PHASE2B-279945-020818	15:14	Soil .	2B				From Roll-off bin 279945 Murky yellow/clear liquid with oil		ļ	
81	NLF-LW-PHASE2B-DINV26-020918	9:10	Liquid	28	RTR-1056			spots floating on top.  Black paint-like liquid from RTR-			
82	NLF-LW-PHASE2B-DINV27-020918	10:38	Liquid	2В	RTR-1064	-		1064			
83	NLF-SS-PHASE2B-9943-021318	15:06	Soil	2B .			,	From Roll-off bin 9943		-	
84	NLF-SS-PHASE2B-PT5628-021418	10:09	Soil .	2B				From Roll-off bin PT5628			